

80%

of all large tires fail before they wear out. Here are some tips that can help extend tire life and keep operators safe on the road.



- Do not speed when going around curves.
- Do not brake excessively.
- Maintain a speed compatible with job site conditions and speed limits.

Loading



- Don't overload the machine. Overloading the machine makes tires more susceptible to punctures & bulging.
- Be sure the load is centered.

Jobsite Conditions



- Avoid water. Water acts like a lubricant which can increase the risk of punctures.
- Stay a safe distance away from highwalls and berms. These raised surfaces may contain rock and other hazards that can slash tire sidewalls.

Walkaround Inspection



- Always perform a machine walk around before and after every shift.
- Thoroughly inspect tires during the walkaround and be sure that they are properly inflated.

CAT® SIMULATORS

learn@catsimulators.com 1.309.266.2640 www.catsimulators.com



